


Wiring Diagram:



Phase	4			
Step Angle	1.8			deg.
	PARALLEL	UNIPOLAR	SERIES	
Voltage	2.74	3.92	5.5	V
Current	5.6	4	2.8	A
Resistance	0.49	0.98	1.96	Ω
Inductance	4.1	4.1	16.4	mH
Holding Torque	6.8	4.7	6.8	N.m
Insulation Class	B			
Mass	3			kg

				www.stepermotorcanada.ca			
2017.02.25							
				JK86HS97-4008-01F			